

Expansion Unit RX418



??????? :: ???????
??? ?????? :: RX418
???? ??????? :: ?? 12 ??? 18 ???
?????: 4.28kg
???????290.00mm x 430.50mm x 44.00mm
???? ??????:

????? ???????

??? ?????? ????????	4
??? ????????	3.5
???? ???? ??????? ??????	yes
????? ??????	40 mm x 40 mm x 3 pcs
???? ????? ??????/??????	100 W
Operating Temperature	5°C to 35°C (40°F to 95°F)
Storage Temperature	-20°C to 60°C (-5°F to 140°F)